


PSP Detailed Report

Sample Report

Federal Motor Carrier Safety Administration

Driver Information												
Last Name	First Name	License #	State									
DOE	JOHN	111111111	VA									
DOE	JOHN	222222222	NY									
Crash Activity (5 year history from MCMIS snapshot date)												
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)												
# of Crashes:	4	# of crashes with Fatalities:	1	# of Crashes with Injuries:	3	# of Towaways:	3					
# Not preventable	1	# of Fatalities:	1	# of Injuries:	4	# of Hazmat Releases:	0					
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)												
	Date	DOT #	Carrier Name	Driver Name	Drive Lic	State	Driver DOB	Rpt St	Rpt Number	Location	# Fatalities	# Injuries
1	10/24/2016	168714	XYZ TRUCKS, INC.	DOE, JOHN	222222222	NY	08/08/1988	VA	VA000000000	I66 EB .5M E RT 29	0	1
2	04/03/2017	168714	XYZ TRUCKS, INC.	DOE, JOHN	111111111	VA	08/08/1988	CA	CA111111111	I 405 NB	1	2
 ROW 2 REVIEWED - NOT PREVENTABLE - FMCSA REVIEWED THIS CRASH AND DETERMINED THAT IT WAS NOT PREVENTABLE.												
3	01/14/2018	345678	XYZ & ABC HAULING	DOE, JOHN	111111111	VA	08/08/1988	NY	NY333333333	I 87 NB	0	1
4	08/28/2019	333444	ABC 123 TRUCKING INC.	DOE, JOHN	111111111	VA	08/08/1988	NJ	NJ444444444	I 95 SB	0	0
Inspection Activity (3 year history from MCMIS snapshot date)												
Inspection Summary												
Driver Summary				Vehicle Summary				Hazmat Summary				
Driver Inspections:	4			Vehicle Inspections:	4			Hazmat Inspections:	0			
Driver Out-of-service Inspections:	2			Vehicle Out-of-service Inspections:	1			Hazmat Out-of-service Inspections:	0			
Driver Out-of-service Rate:	50%			Vehicle Out-of-service Rate:	25%			Hazmat-Out-of-service Rate:	0%			

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Report executed at: 5/4/2020 2:42:16 PM
MCMIS snapshot date: 04/24/2020

For an explanation of FMCSA-reportable crashes see <https://www.psp.fmcsa.dot.gov/psp/FAQ.aspx>.

Sample Report

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Drive Lic	State	Driver DOB	Rpt St	Rpt Number	Hazmat Insp	Insp Level	# of Viol
1	01/18/2018	475002	123 ABC TRUCKING	DOE, JOHN	111111111	VA	08/08/1988	LA	1111111111	N	1	3
Vehicle Violation: 393.47(e)				CLAMP/ROTO TYPE BRAKE(S) OUT-OF-ADJUSTMENT			NON-OOS					
Vehicle Violation: 393.95(f)				NO/INSUFFICIENT WARNING DEVICES			NON-OOS					
2	07/24/2018	345678	XYZ & ABC HAULING	DOE, JOHN (co-driver)	111111111	VA	08/08/1988	VA	222222222	N	1	1
Vehicle Violation: 393.42(a)				INOPERATIVE OR MISSING BRAKE			OOS – This violation does NOT apply to DOE, JOHN.					
3	08/22/2018	345678	XYZ & ABC HAULING	DOE, JOHN	111111111	VA	08/08/1988	CA	333333333	N	1	1
Co-Driver Violation: 393.45				Brake tubing and hose adequacy			NON-OOS – This violation does NOT apply to DOE, JOHN.					
4	09/04/2019	333444	ABC 123 TRUCKING INC.	DOE, JOHN	111111111	VA	08/08/1988	WA	444444444	N	1	3
Driver Violation: 392.5(a)(2)				DRIVING UNDER THE INFLUENCE			OOS					
State Citation#: TX568552 State Citation Result: Convicted of different charge												
Driver Violation: 395.3(a)(3)(i)				DRIVING BEYOND 11 HOUR RULE			OOS					
Violation Summary												
Violation #	Description							# of Violations	# of Out-of-service Violations			
393.47(e)	CLAMP/ROTO TYPE BRAKE(S) OUT-OF-ADJUSTMENT							1	0			
393.95(f)	NO/INSUFFICIENT WARNING DEVICES							1	0			
393.42(a)	INADEQUATE BRAKE SYSTEM ON A CMV							1	1			
395.3(a)(3)(i)	DRIVING BEYOND 11 HOUR RULE							1	1			
392.5(a)(2)	DRIVING UNDER THE INFLUENCE State citation result: Convicted of different charge							1	0			

The summary counts and rates only include violations that were attributable to DOE, JOHN.

Report executed at: 5/4/2020 2:42:16 PM
MCMIS snapshot date: 04/24/2020

For an explanation of FMCSA-reportable crashes see <https://www.psp.fmcsa.dot.gov/psp/FAQ.aspx>.

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.